







A	x40
	
M6*35mm	


B	x40
	
φ 15*10mm	


C	x16
	
M6*30mm	


D	x22
	
M4*35mm	


E	x48
	
M3.5*12mm	


F	x4
	


G	x8
	
M3*16mm	





H	x2
	


I	x2
	



J	x2
	
M4*12mm	


K	x8
	





 45 MIN		 NOT PROVIDED	
---	--	---	---





		x4
---	---	-----------



A	x16
	

E	x24
	



F	x4
	



2





B	x8	C	x6
			

3





B	x8	C	x6
			

4




A	x4

5
















B	x4	C	x4



6





x4



 <p>DL DR x4</p>	<table border="1"> <tr> <td>A</td> <td>x20</td> </tr> <tr> <td></td> <td></td> </tr> </table>	A	x20			<table border="1"> <tr> <td>B</td> <td>x20</td> </tr> <tr> <td></td> <td></td> </tr> </table>	B	x20			<table border="1"> <tr> <td>D</td> <td>x20</td> </tr> <tr> <td></td> <td></td> </tr> </table>	D	x20			<table border="1"> <tr> <td>E</td> <td>x24</td> </tr> <tr> <td></td> <td></td> </tr> </table>	E	x24		
A	x20																			
																				
B	x20																			
																				
D	x20																			
																				
E	x24																			
																				

7





8



K	x8		x8
			

9



D	x2	J	x2	H	x2	I	x2
