




**OAK KONSOLIPÖYTÄ, 2 LTK, NATURAL TAMMI/ TAMMIVIILU**

**198065**






**Ax14**



**Bx14**




**Cx4**



**Dx4**



**Ex4**



**Fx8**



**Gx18**



**Hx8**




**Jx4**



**Kx4**



**Lx4**



**Mx1**




**Nx4**



**Px2**




**Qx2**



# 1


Ax14 



# 2




Hx8 


Nx4 





3-8


# 3

- Ex4 
- Px2 
- Qx2 




# 4

- Dx4 
- Mx1 



# 5

Bx2



# 6


Bx2



Cx2








Kx2



5-8


7

- Bx2 
- Cx2 
- Kx2 
- Lx4 




8

- Gx18 




# 9

Bx8





# 10

Fx8





# 11

Jx4 



# 12



8-8